































## Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле  $W = 3Д - 2Ш - С$ .

<p><b>Вариант 1</b> Д22.</p> 	<p><b>Вариант 2</b> Д22.</p> 
<p><b>Вариант 3</b> Д22.</p> 	<p><b>Вариант 4</b> Д22.</p> 
<p><b>Вариант 5</b> Д22.</p> 	<p><b>Вариант 6</b> Д22.</p> 
<p><b>Вариант 7</b> Д22.</p> 	<p><b>Вариант 8</b> Д22.</p> 
<p><b>Вариант 9</b> Д22.</p> 	<p><b>Вариант 10</b> Д22.</p> 





Ответы

1	2
2	6
3	0
4	1
5	-1
6	2
7	5
8	3
9	4
10	4
11	1
12	1
13	4
14	0
15	0
16	3
17	0
18	1
19	3
20	4
21	4
22	1
23	5
24	2
25	4
26	3
27	4
28	1
29	2
30	4